



expose 150-200mm of cable core.

NB There is a spare blade in the handle of longitudinal cuts on the cable sheath to Using correctly adjusted Strippers Cable Sheath 7, make two diametrically opposite this tool






members to a length of 20mm



required length. Pull slowly to split the cable sheath to the suitable bar (eg handle of nippers). Extract the rip cord and wrap it around a



members and sheath Protection 2A over the strength sheath and place a Sleeve Dropwire Fold back strength members along